

Business Name: Reach Dental Equipment Repair

Name: Stanley Lumapas

Address: 3224 SE Concord Rd

City: Portland

State: OR

Zip: 97267

Phone: 503-453-3177

Fax:

Email: slumapas@msn.com

Comments/Notes: Unit seems to function properly other than the service light during the purge cycle. It does not go away until the unit is power cycled. Foot control needs a new screw for the battery cover.

Equipment: Small Equipment Repair

Item #	Quantity	Make	Model	S/N	Problem
1	1	Dentsply	Cavitron Plus	G136-14878	Service light comes on during purge cycle

Tracking Code: 1Z65VV921219406697