

Business Name: Fisher Dental

Name: Kili Maggard

Address: 328 S 2nd St

City: Coos Bay

State: OR

Zip: 97420

Phone: 5412692100

Fax:

Email: office.fisherdental@gmail.com

Comments/Notes: All of these handpieces have been set aside for quite some time because they were not working properly. I am unsure on exact issues with any of them. There is one slow speed w/ a bur stuck in it. Thank you.

Equipment: Handpiece Repair

Item #	Quantity	Make	Model	S/N	Problem
1	2	Brasseler	LS1L Contra Angle Attachment	E8535360, E8535354	One has a bur stuck. The other spins and gets hot.
2	3	A-dec / W&H	Synea 400 series TG-97 L	015630, 016287, 009560	I am unsure what the problems are with these. One of them may be leaking oil the package says.
3	1	A-dec / W&H	Synea HS TA-96 Lw	08883	When a bur is put into the head, it wobbles.

Tracking Code: 1Z65VV921237653136