

Business Name: Fix It Biomedical

Name: Adam Burkhart

Address: 14317 Potranco Rd, Ste 205/109

City: San Antonio

State: TX

Zip: 78245

Phone: 210-428-1190

Fax:

Email: fixitbiomedical@gmail.com

Comments/Notes: No water through motor. Water is flowing through another motor on same handpiece tubing. Contacted Kavo and they said the check valve inside the motor needs to be replaced. Please replace the check valve.

---

Equipment: Handpiece Repair

---

Item #	Quantity	Make	Model	S/N	Problem
1	1	Kavo	KL 703 LED	14-1022172	No Water

---

Tracking Code: 1Z65VV921209903212