

Business Name: Sooner Dental Equipment

Name: Richard Lay

Address: 4545 Annette Ct.

City: Merritt Island

State: FL

Zip: 32953

Phone: 4054737741

Fax:

Email: richard.lay@soonerdentalequipment.com

Comments/Notes: For the two Brasseler parts, please only repair the part that is testing badly. The office just told me "not working" for that, so I took it all. If both the head and body of the handpiece are broken, then you can repair both.

Equipment: Handpiece Repair

Item #	Quantity	Make	Model	S/N	Problem
1	1	Brasseler USA	LS1	E0945804	Not Working
2	1	Brasseler USA	LSL	A094114	Not Working
3	1	Unknown	L A	A7732166	Won't hold bur
4	1	Kavo	Mastermatic LUX 25 L	2021-1059896	Keeps getting hot

Tracking Code: 1Z65VV920324211485