Business Name: Talon Dental Maintenance LLC

Name: Mark McNeese

Address: 4209 E Tanglewood Dr

City: Phoenix State: AZ Zip: 85048

Phone: 4803697741

Fax:

Email: mark@talondental.com

Comments/Notes: Sorry less foot control, was run under ground. Dr asked if a hand piece holder can be added

to the right side of unit. Thank you

Equipment: Small Equipment Repair

Item # Qua	ntity Make	Model	S/N	Problem
1 1	Parke	D560 Turbo Sensor	209349	Leaks water, no water adjustment.

Tracking Code: 1Z65VV921216443572